





خیتان پاور

کھیتان پاور

KHAITAN POWER

EXPECT THE BEST



KI C5SB W
MARBLE CUTTER

EXPLOSION VIEW

Industrial Series



SPARE PARTS LIST OF KI C5SB W

DWG NO.	Description	Unit	DWG NO.	Description	Unit
1	Fan Baffle	1	32	Front Cover	1
2	Stator	1	33	Oil Seal	1
3	Spring	2			
4	Locking Cap	1	35	Ball Bearing 6002	1
5	Handle Cover	1	36	Circlip	1
			37	Output Shaft	1
7	Switch	1	38	Big Gear	1
8	Motor Housing	1	39	Ball Bearing 626	1
9	Screw M5x30	3	40	Gear Housing	1
10	Screw ST4x16	7	41	Ring	1
11	Label	1	42	Small Gear	1
12	Dust Proof Net	1	43	M7 Nut	1
13	Screw ST5x8	2	44	Ball Bearing 629	1
14	Brush Holder	2	45	Bearing Washer	1
15	Carbon Brush	2	46	Key	1
16	Brush Holder Cap	2	47	Armature	1
17	Cable Wire	1	48	Bearing Washer	1
18	Cable Shealth	1	49	Ball Bearing 608	1
19	Cable Plate	1	50	Bearing Sleeve	1
20	Screw ST4x14	2	51	Base Ass'y	1
21	Right Assist Handle	1	52	M5 Nut	1
22	Left Assist Handle	1	53	Screw Pin	1
23	Screw 4x20	1	54	Washer	1
24	Right Dust Exit	1	55	Screw Nut M6x10	1
25	Left Dust Exit	1	56	Wrench A	1
26	Screw ST5x65	1	57	Wrench B	1
27	Screw M8X16	1	58	Dust Bag	1
28	Upper Flange	1	59	Dust Pipe	1
29	Down Flange	1	60	Front Dust Cover	1
30	Flange Washer	1	61	Screw M4x8	2
31	Screw 5x16	4	62		