





KI SMS 12 12" SLIDING MITER SAW





SPARE PARTS LIST OF KI SMS 12

art No.	description
1	Cross recessed pan head tapping screw ST4.2X14(black)
2	Housing label
3	Motor back cover
4	Carbon brush cap
5	Carbon brush assembly
6	Carbon brush holder assembly
7	Inner hexagon screw M4X6(black) Cross recessed pan head screw
8	M5X35 (zincing)
9	Spring washer 5(zincing)
10	Flat washer 5(zincing) ¢5x¢10x1
11 12	Label Motor housing
13	Rubber bearing support (NBR)
14	Bearing(6000-2z)
15	Field assembly
16	Field connecting wire(18AWG)
17	Flat washer 5(black) ⊄5x⊄10x1
18	Cross recessed pan head tapping screw ST4.8X70(black)
19	Baffle(in black)
20	Armature assembly
21	Bearing (6202-2RS)
22	Spindle lock knob(in black)
23	Spindle lock plate(zincing)
24	Spindle lock pin 45#(black and quench)
25	Spindle lock spring(65Mn)
26	Cross recessed countersunk head
27	screw M4X8(zincing) Upper guard(silver)
28	Bearing (HK1016)
29	Bull gear(black)
30	Shaft Circlips 14
31	Flat key 5X12 (black)
32 33	Output shaft
34	Hole circlip 40(black) Bearing (6203-2 RS)
35	Top cover
36	Cross recessed countersunk head
37	screw M5X16(black with thread R9Cker)05x7(Zincing)
38	Plastic Lower guard
39	AL blade guard
40	Lower guard spring(black)
41	Shaft Circlips 45
42	Shaft sleeve(in black)
43	Inner flange(black)
44	Blade Outer florge(block)
45 46	Outer flange(black) Flange screw(black)
47	Lower guard rolling wheel(in black)
48	Flat washer 3(¢3X¢10X1)
49	Blade cover warining label
50	LED support(black)
51	LED viewfinder(chrome plating)
52	LED lamp
53	LED glazing(clear) Cross recessed pan head screw
54	M5X40(zincing)
55	Upper guard self-lock spring(black)
56	Safety lock handle(in black)
57 58	Loose-proof nut M5(zincing) Safety lock support(zincing)
	Cross recessed pan head screw
59	M5X10(zincing)
60	Cross recessed pan head screw M5X14(zincing)
61	Handle connecter

Dont	
Part No.	description
63	Height adjustment knob(black) with
64	M5x55 screw Inner hexagon screw M6X20(black)
65	Nut M6(Zincing)
66	Height adjustment nut(black)
67	Laser label
68	Spring wheel(in black)
69	Step screw(black)
70	Cross recessed pan head screw M5X16(zincing)
71	Handle assembly
72	Cross recessed pan head screw M5X45(zincing)
73	Cross recessed pan head tapping screw ST4.2X16(black)
74	Top Handle overmold
75	Transformer
76	Cord clamp
77	Inductor
78	Plug 2x1.0 with wire clamp, 3m rubber cable
79	Laser and LED connecting line 24AWGx2
80	Cord sleeve(in black)
81 82	Terminal block(two) Terminal block(three)
83	Capacitance
84	Laser switch
85 86	LED switch Lower handle overmold
87	Working light transparent cover
88 89	Working light Switch trigger(light grey)
90	Connecting wire A inside handle(18AWG white)
91	Connecting wire B inside handle(18AWG brown)
92	Loose-proof nut M12(zincing)
93 94	Flat washer D12(zincing) ¢10x¢24x2 Sleeve(black)
95	Torsion spring(black)
96 97	Height adjustment step screw(black) Height adjustment plate(zincing)
98	Wave washer 6(black)
99	Hexagon screw M6X20(zincing) Spring washer D6(zincing)
101	Flat washer D6(zincing)
102 103	Bracket stop pin Bracket for upper guard
104	0 washer 4.5*8.1*1.8 (rubber)
105 106	Bevel lock pin cap(in black) Bumper(in black)
107 108	Torsion spring sleeve(in black) Lever screw(black)
109	Pivot pin for upper guard(black)
110	Inner hexagon screw M5X6(black with thread locker)
111	Laser set B
112 113	Laser Laser set A
114	Laser transparent plate
115 116	Inner hexagon screw M5X20(zincing) Laser support C(black)
117	Cross recessed pan head tapping
118	screw ST3X8(black) Winding support(black)
119	Flat washer D4 (zincing)
120 121	Spring washer D4(zincing) Cross recessed pan head screw
122	M4X8(zincing) Lower guard back cover locating
123	screw(black) Lower guard cover rivet(black)
124	Lower guard cover on right
125 126	Lower guard cover on left Lower guard lever(black)
127	Lower guard cover step screw(black)
128 129	Lever locating screw(black) Lower guard cover lever(black)
	Lower guard lever rivet(black)
130	Linear rod support bracket
131	Cross recessed countersunk head
131 132	screw M5X10(black)
131	

Part No.	
No.	Janamiatian
	description
	Bevel angle scale indicator(clear
137	with a red line)
138	Bearing support(black)
139	Linear rod support bracket lock
	knob(light grey) Linear rod support bracket lock
140	handle spring(black)
141	Linear rod support bracket lock
	handle(dark grey)
142	Nut M10(7mm with zincing)
143	Pivot pin for linear rod support bracket(black)
144	Flat washer D10 ¢10x¢20x2(zincing)
145	Friction washer(black)
146	Linear rod support bracket arm
147	Bevel angle lock pin(black)
148 149	Inner hexagon screw M8X45(black) Flat washer D8(black)
150	Angle of labeling
151	Inner hexagon screw M5X20(black)
152	Inner hexagon screw M8X30(zincing)
153	Nut M8(zincing)
154	Table pivot bracket
155 156	Slotted plate Turning table
	Cross recessed countersunk head
157	screw M4X10(zincing)
158	Pin on the table lock handle
	¢2.5X16(zincing)
159 160	Locking cam(black) Cam pin(black)
161	Turning table lock handle plate
162	Turning table lock handle
163	Spring washer 5(black)
164	Cross recessed pan head screw
165	M5X10(black) Inner hexagon screw M6X20(black)
166	Spring washer D6(black)
167	Flat washer D6(black)
168	Base screw(black)
169	Fence
170 171	Base Fence Label
172	Base warning Label
173	Wave washer 12 (black)
174	Base Scale label
175	Left extension bar
110	
176	Balancing pole
176	Right extension bar
176 177	
176 177 178 179 180	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter
176 177 178 179 180 181	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black)
176 177 178 179 180 181 182	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing)
176 177 178 179 180 181 182 183	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black)
176 177 178 179 180 181 182	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing)
176 177 178 179 180 181 182 183 184 185	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black)
176 177 178 179 180 181 182 183 184	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black)
176 177 178 179 180 181 182 183 184 185	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw
176 177 178 179 180 181 182 183 184 185 186 187	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black)
176 177 178 179 180 181 182 183 184 185 186 187 188	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line)
176 177 178 179 180 181 182 183 184 185 186 187 188	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 & 10x & 14x1(zincing)
176 177 178 180 181 182 183 184 185 186 187 188 189	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 & Clox & l4x1(zincing) Miter lock front plate(black)
176 177 178 179 180 181 182 183 184 185 186 187 188	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 & Clox & l4x1(zincing) Miter lock front plate(black)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 & D10x & 14x1(zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle plate(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer DlO & Dox & Jax (zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock front lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer D10 & 10x & 14x1(zincing) Miter lock front plate(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle plate(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Spring pin 03x16(black) Spring pin 03x16(black)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle plate(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer DlO & lox&laxl(zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M8X35(zincing) Allen wrench M8 Working clamp knob(light grey) Spring pin 03x16(black) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp rod(zincing)
176 177 178 179 180 181 182 183 184 185 186 187 188 199 190 191 192 193 194 195 196 197 198 199 200 201	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer Dl0 & 10x & 14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp plate(black) Working clamp plate(black) Working clamp plate(black) Working clamp plate(black)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp plate(black) Working clamp plate(black) Butterfly screw(assembly)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 199 200 201 202 203	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring (black) Loose-proof nut M8 (zincing) Miter lock middle lever (black) Miter lock middle plate (black) Miter lock middle plate (black) Inner hexagon screw M8X10 (black) Turning table locking screw (black) Cross recessed pan head screw M4X10 (zincing) Turning table angle scale indicator (clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate (black) Spring pin 04x25 (black) Balancing Foot(light grey) Cross recessed pan head screw M6X35 (zincing) Allen wrench M8 Working clamp knob (light grey) Spring pin 03x16 (black) Working clamp plate (black) Butterfly screw(assembly) Working clamp plate (black)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp plate(black) Working clamp plate(black) Butterfly screw(assembly)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin Ø4x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp arm(dark grey) Spring pin Ø3x16(black) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (\$5X\$9X0.8) Flat washer 5 (\$5X\$9X0.8)
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 199 200 201 202 203 204 205 206 207	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring (black) Loose-proof nut M8 (zincing) Miter lock middle lever (black) Miter lock middle plate (black) Miter lock middle plate (black) Inner hexagon screw M8X10 (black) Turning table locking screw (black) Cross recessed pan head screw M4X10 (zincing) Turning table angle scale indicator (clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate (black) Spring pin 04x25 (black) Balancing Foot(light grey) Cross recessed pan head screw M6X35 (zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16 (black) Butterfly screw(assembly) Working clamp rad(zincing) Working clamp sliding rod(black) Cord quoit Flat washer 5 (\$5X\$\$10X1) Wrench holder
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle plate(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer DlO & lox&laxl(zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M8X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Butterfly screw(assembly) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 4 (\$5X\$10X1) Wrench holder Cross recessed pan head screw M5X8
176 177 178 179 180 181 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring (black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer Dl0 & Dlox & Dlox & Dlox & Dlox Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 04x25(black) Butterfly screw(assembly) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (\$5X\$\$9X0.8) Flat washer 4 (\$5X\$\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208	Right extension bar Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle plate(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer DlO & lox&laxl(zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M8X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Butterfly screw(assembly) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 4 (\$5X\$10X1) Wrench holder Cross recessed pan head screw M5X8
176 177 178 179 180 181 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Miter lock plate(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer DlO & lox & l4x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 4 (\$5X\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Sliding fence Fence left label Fence right label
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 207 208 206 207 208 209 210 211 212 213	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer Dl0 & Dlox & 14x1(zincing) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp knob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Butterfly screw(assembly) Working clamp plate(black) Butterfly screw(assembly) Working clamp plate(black) Crod quoit Flat washer 5 (\$5x\$9X0.8) Flat washer 4 (\$5x\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Sliding fence Fence left label Fence right label connector
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 200 201 203 204 205 207 208 209 210 211 212 213 214	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp arm(dark grey) Spring pin 03x16(black) Butterfly screw(assembly) Working clamp sliding rod(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (&5X\$9X0.8) Flat washer 5 (&5X\$9X0.8) Flat washer 4 (\$5X\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Sliding fence Fence left label Fence right label Fonce right label Fonce left label Fence right label Fonce right label
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 200 201 200 201 202 203 204 205 206 207 208 209 211 212 213 214 215	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring (black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Cross recessed pan head screw M4X10(zincing) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp shob(light grey) Working clamp arm(dark grey) Spring pin 03x16(black) Working clamp plate(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (\$5x\$\$\psi\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Spring pin 04x25(black) Butterfly screw (assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (\$5x\$\$\psi\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Sliding fence Fence left label Fence right label Connector LOGO Label Turning table label
176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 200 201 203 204 205 207 208 209 210 211 212 213 214	Right extension bar Miter lock spring lever(black) Miter lock spring lever(black) Steel ball in 8mm diameter Miter lock spring(black) Loose-proof nut M8(zincing) Miter lock middle lever(black) Miter lock middle lever(black) Miter lock middle plate(black) Inner hexagon screw M8X10(black) Turning table locking screw(black) Turning table angle scale indicator(clear with a red line) Flat washer D10 &10x&14x1(zincing) Miter lock front plate(black) Miter lock back lever(black) Spring pin 04x25(black) Balancing Foot(light grey) Cross recessed pan head screw M6X35(zincing) Allen wrench M8 Working clamp arm(dark grey) Spring pin 03x16(black) Butterfly screw(assembly) Working clamp sliding rod(black) Butterfly screw(assembly) Working clamp sliding rod(black) Cord quoit Flat washer 5 (&5X\$9X0.8) Flat washer 5 (&5X\$9X0.8) Flat washer 4 (\$5X\$10X1) Wrench holder Cross recessed pan head screw M5X8 Butterfly screw Sliding fence Fence left label Fence right label Fonce right label Fonce left label Fence right label Fonce right label